



3 AMP FUSE SPUR (BY OTHER)

VALVE

N/C OR N/O TERMINAL

Transducer should be screwed into the DOWNSTREAM PORT on the gas solenoid valve normally situated on the base of the valve.

EM STOP (VOLT FREE)



NOTES:
NO VOLTAGE ABOVE 24V SHOULD BE PUT INTO THE NC TERMINALS

Rev.	Drawn	Chkd.	Apprvd.	Date	Description
-	?	?	?	?	PRELIMINARY

Project
SNS NORTHERN

Drawing Title
1000GD DIAGRAM



Unit 2, Dickinsons Industrial Estate, Moss Lane, Coppull, Chorley, PR7 5AL
Tel: 01257 470 983 Fax: 01257 471 937 Email: info@snsnorthern.com

Scale (at A1)	Date	Drawn
NOT TO SCALE	11/11	SJB

Dwg. no.	Rev.
JOB-DWG-NO	-